

RAILWAY Track and Structures

Simmons-Boardman Publishing Corporation

Volume 64

January-December 1968

General Article Index

- (*) Illustrated article
- (A) What's the answer?
- (E) Editorial
- (F) For your information
- (L) Letter to the editor

American Railway Bridge & Building Assn.: Meeting in September, *Sept 30 Why it is needed, *Oct 22 American Railway Engineering Association: Meeting sets a record, *Apr 17 What membership offers railroad engineer, *Mar 25 American Swedish Rail System: Concrete roadbed and fastenings, *May 30 Anchors: SCL standard practice on merged line, *Jan 20 Armcro Steel Corp.: Culvert cunning: Design and repairs, *Dec 17 Liner plates cure rock falls in tunnel, *Jan 26 Association of American Railroads: Size and spacing of wood ties, *July 22 Atchison, Topeka & Santa Fe: Treats deck timbers on bridges in place, *Feb 32 Ballast: Ballast care and maintenance, Sept 10E From steel-furnace slag, *June 22 Keeping sand out (A), Oct 40 Replacing on ballasted-deck (A), Aug 36 Section for ladder tracks (A), Mar 76 Bangor & Aroostook: Coping with snow in North Country, *Aug 15 Branch Lines: Inspection of (A), June 36 Bridge and Building Work: Tools and equipment, Sept 42 Bridges: B&O installs longest girders, *June 17 B&B supervisor and fire prevention (A), Dec 35 Computer design of piers, *Nov 24 Concrete ties for timber trestles, *Sept 25 Covered bridges—Can they be saved?, *Feb 27 Deck timbers treated in place, *Feb 32 Effects of E-80 loading (A), May 34 Fastening timber stringers to concrete caps, *Sept 36 Framing ties for plate girders (A), Feb 46 Frisco photographs its clearances, *Apr 22 Inspection of prestressed-concrete spans (A), Nov 37 Latest development of in-place treatment, Sept 33E Long cars and through girders (A), Mar 70 Maintaining signal bridges (A), Apr 30 New one goes around old, *July 26 Obsolete structure cut down with explosives, *Apr 25 Painting—Where are we headed?, *June 24 Preserving sandblasting results (A), June 29 Repairing expansion rollers, Sept 36E Replacing ballast on deck (A), Aug 36 Replacing timber caps with concrete (A), July 34 Research and progress in, *Jan 22 Selection of expansion bearings (A), Sept 48 Selection of piles (A), Jan 42 Should timber decks be waterproofed (A), July 33

Type of waterproofing (A), July 36 Use of weathering steel (A), Oct 42 Using oak ties (A), Aug 39 Buildings: Advantages of prefabricated concrete (A), Jan 33 Inspection pointers (A), Mar 68 Where to use fiberglass (A), June 34 Chesapeake & Ohio/Baltimore & Ohio: Installs 'longest' girders, *June 17 Chicago, Burlington & Quincy: Upgrades its tie-renewal gangs, *Dec 14 Chicago, Milwaukee, St. Paul & Pacific: Gang nails protect crossing timbers, *July 20 Clearances: Frisco photographs its clearances, *Apr 22 Cleveland Transit System: Extends line with welded rail, *Oct 24 Communications: Make them work for you, Sept 28E Concrete and Concrete Work: Adjustments easy on concrete roadbed, *May 30 Concrete ties for timber trestles, *Sept 25 Fastening timber stringers to concrete caps, *Sept 36 High-speed impact stresses on (A), Jan 23 Prefabricated concrete for buildings (A), Jan 33 Prestressed-concrete span inspection (A), Nov 37 Replacing timber caps (A), July 34 U.S. Crosstie plant in production, *May 26 When to use anchor bolts (A), Feb 35 Conventions and Meetings: AREA meeting sets a record, *Apr 17 Roadmasters' & B&B meeting, *Sept 30 Speakers tell needs and prospects, *Oct 17 Crossings: Gang nails protect timbers, *July 20 Safety demands elimination (L), Feb 50 Stockpiling black-top for highways (A), Jan 36 Culverts: Common causes of failure (A), Sept 60 Culvert cunning; Design and repairs, *Dec 17 Curves: Long cars and through girders (A), Mar 70 Merits of long transition (A), Sept 40 Record of wear (A), July 32 Department of Transportation: DOT proposal portends new era in M/W (E), May 8 Engineers as seen by A. Scheffer Lang, *May 24 To engineers: Assert yourselves (E), May 8 Derailed: Clearing up (A), Dec 28 Stopping before they happen (E), Oct 8 Employees: Another reason for thinking of women (E), Sept 12 Award 298 and the M/W forces, Aug 22 Centralized B&B vs floating gangs, Sept 41E DOT to engineers: Assert yourselves (E), May 8 Effect of arbitration award (A), July 36 Engineers as seen by A. Scheffer Lang, *May 24 Is engineering degree necessary? (E), Jan 8 Manpower shortage could get worse (E), Aug 12 Role of M/W men in mechanization (E), Mar 8 Salute to short-line engineers (E), Dec 8 Steps to help the bridge engineer (E), July 8 Watching passing trains (E), Oct 8 Where will we get supervisors? (E), Apr 8 Erie Lackawanna: How road lays long strings, *Oct 26 Machines lick brush problem, *Aug 24 Explosives: Used to cut down bridge on Frisco, *Apr 25 Fairmont Railway Motors: W110 Series C Dual Tamper, Mar 40 Fire: Old apparatus fills railroad need (E), Mar 8 Responsibility of B&B supervisor (A), Dec 35 Garo Art Metal, Inc.: Sculptured track spike, *Dec 22 Glued Laminated Timber: Research and progress in bridges, *Jan 22 Hydraulics: What test bench did for Reading, *Nov 22 Inspection: Branch lines (A), June 36 Pointers for building inspection (A), Mar 68 What track inspection should be, Sept 14E Where to run detector car (A), Apr 32 Jackson Vibrators, Inc.: Model 4500 surfacing-liner unit, *Mar 38 Model 4500 seen in operation on SCL, *July 24 Joints: Will longer bars eliminate pull-aparts?, Mar 74 Kershaw Manufacturing Co.: Announces \$5 million plant expansion, *Nov 42 Tie Injector used by Burlington, *Dec 14 Linde Division, Union Carbide: Cored-wire electrode for rail-end build-up, *June 20 Louisville & Nashville: Cures rock falls in tunnel, *Jan 26 Maintenance of Way: Burlington upgrades tie-renewal gangs, *Dec 14 Computer system hikes machine output, *Mar 34 Coping with wind-driven sand (A), July 34 Coping with snow in North Country, *Aug 15 Disposing of cut-up ties (A), Sept 54 Distributing ties for gangs (A), Dec 34 DOT proposal portends new era for M/W (E), May 8 Future historian looks back upon (E), Dec 8 How to improve maintenance, Sept 21E Improving track despite worn rail (A), Oct 32 Improvements—Where, how?, Nov 26 Is there need for more supervision? (E), Nov 8 Keeping sand out of ballast (A), Oct 40 Keeping shifting sands off the tracks, *Aug 19 Merits of long transition curves (A), Sept 40 Need to spend more on, *Oct 18 Radio and M/W forces, *May 20 Reconciling standards of merged roads, *Jan 19 Some rule books need updating (E), Aug 12 Spike reclamation on the job, *Sept 32 Staff report on Award 298, Aug 22 Stopping derailments before they happen (E), Oct 8 The importance of track improvements (E), July 8 Turnouts and good intentions (E), Oct 8 Use of secondhand materials in yards (A), Jan 40 What welded-rail records to keep (A), Feb 38 Where will we get supervisors? (E), Apr 8

Who got the large savings? (E), Apr 8
 Who maintains signal bridges? (A), Apr 30
Management:
 Attitude toward weed control (E), Feb 8
Matisa Equipment Corp.:
 BMNRL-80 Automatic tamper-liner, *Mar 38
 Ballast Cleaner-Undercutter used on MP, *Dec 23
Mechanization:
 Where do we go from here?, *Mar 31
Mergers:
 SCL girds for the future, *Jan 15
Missouri Pacific:
 Computer system hikes machine output, *Mar 34
 Hot, dry climate causes complications on new-line job, *Nov 17
 Push-button plant cuts rail-welding costs, *Feb 30
 Undercutting restores grades to yard, *Dec 23
Motor Cars:
 Are they getting heavier? (E), Feb 8
National Cylinder Gas Division:
 Scan used on Frisco, *Apr 22
New Lines:
 Hot, dry climate causes complications, *Nov 17
Nordberg Manufacturing Co.:
 Spike reclamation on the job, *Sept 32
Osmose Wood Preserving Co.:
 Treat deck timbers in place on Santa Fe, *Feb 32
Painting:
 Preserving results of sandblasting (A), June 19
 Where is bridge painting headed?, *June 24
Penn Central:
 Devises cribber for Joint Straightener, *Jan 27
 Tries out Plasser track-lining machine, *Sep 34
Piers and Foundations:
 Computer design of for UP, *Nov 24
Piles:
 Selection of for bridges (A), Jan 42
Plasser American Corp.:
 Duomatic 06-32L continuous automatic tamper-liner, Mar 39
 Model AL 250 Automatic Lining machine, *Sep 34
Portec, Inc.:
 Opens new plant in Oakbrook, *Nov 42
Prestressed Concrete:
 Inspection of spans (A), Nov 37
 Research and progress in bridges, *Jan 22
 SCL standard practice for ties, *Jan 20
Programming:
 Effect of arbitration award (A), July 36
Pumps:
 What types for B&B crews? (A), Aug 35
Racine Hydraulics, Inc.:
 Ballast cribber for joint straightening, *Jan 27
Radio:
 How it helps M/W forces, *May 20
 Make communications work for you, Sept 28E
Rail:
 Broken from heavy cars (A), May 44
 Broken-wire electrodes for rail-end build-up, *June 20
 Correcting pull-aparts in winter (A), June 28
 Improving track despite worn rail (A), Oct 32
 Keeping record of curve wear (A), July 32
 Merits of surface grinding, Sept 7E
 Where to run detector car (A), Apr 32
Rail Laying:
 How the EL lays long strings, *Oct 26
 Positioning CWR before laying (A), Nov 31
 SCL gang uses two sets of machines, *July 17
Railway Maintenance Corp.:
 Cribber devised for Joint Straightener, *Jan 27
 Datamatic automatic tamper-liner, *Mar 39
Railway Tie Association:
 Size and spacing of wood ties, *July 22
Reading:
 What test bench did for railroad, *Nov 22

Roadmasters Association:
 Meeting in September, *Sept 30
 Why it is needed, *Oct 22
Safety:
 Appliances on machines, Sept 2E
 How to enforce rules (A), Nov 34
 Picking up debris in yards (A), Apr 30
 Safety Bureau lists inadequate maintenance, *Oct 18
 Some rule books need updating (E), Aug 12
 Where to run detector car (A), Apr 32
St. Louis-San Francisco:
 Cuts obsolete bridge down with explosives, *Apr 25
 Photo graphs its clearances, *Apr 22
Schnoeder Brothers Corp.:
 New test bench on Reading, *Nov 22
Seaboard Coast Line:
 Gang uses two sets of machines, *July 17
 Improved tamper seen in operation, *July 24
 Newly merged line girds for future, *Jan 15
Southern:
 Concrete ties for timber trestles, *Sept 25
Southern Pacific:
 New bridge goes in around old, *July 26
 Trouble at Potrero Hill tunnel, *Dec 20
Spikes:
 Reclamation on the job, *Sept 32
 Sculptured spike by Garo Art Metal, *Dec 22
Stations:
 Low or car-floor level platforms (A), June 35
Supervision:
 B&B supervisor and fire prevention (A), Dec 35
 Does it get enough recognition? (E), Sept 12
 How roadmasters keep abreast (A), Oct 43
 Is there need for more (E), Nov 8
 We can point to future leaders (E), Nov 8
 Where will we get supervisors? (E), Apr 8
Surfacing and Lining:
 Track-lining machine keeps moving, *Sept 34
Switch Stands:
 Maintaining run-through stands (A), Apr 36
Tamper, Inc.:
 Model UDEJ2.5D3 Electromagnetic tamper with Curve Autoliner, *Mar 39
Thermex Metallurgical, Inc.:
 Used to butt-weld transit line extension, *Oct 24
Ties:
 Burlington upgrades its tie gangs, *Dec 14
 Concrete for timber trestles, *Sept 25
 Disposing of cut-up ties (A), Sept 54
 Distributing for gangs (A), Dec 34
 Framing for deck girders (A), Feb 46
 Kind, size and spacing, Sept 23E
 New concrete-tie plant in production, *May 26
 Standard practices for merged line, *Jan 20
 Uses shock waves in treating oak (F), Aug 44
 Using oak ties on bridges (A), Aug 39
 What size, spacing—wood tie, *July 22
Timber:
 Fastening stringers to concrete caps, *Sept 36
 Gang nail protect crossing timbers, *July 20
 Latest developments of in-place treatment, Sept 33E
 Replacing caps with concrete (A), July 34
 Should timber decks be waterproofed? (A), July 33
 Testing for decay, *Jan 24
 Treats bridge deck in place, *Feb 32
Track:
 Cleaning wind-driven sand from (A), July 34
 How to improve maintenance, Sept 21E
 Improvements—Where, how?, Nov 26
 Improving despite worn rail (A), Oct 32
 Merits of long transition curves (A), Sept 40
 Spike reclamation on the job, *Sept 32
 The importance of improvements (E), July 8
 Track-lining machine keeps moving, *Sept 34
 Undercutting restores grade in yard, *Dec 23
 What inspection should be, Sept 14E
Trackwork:
 Use of rivets where possible (A), May 33

Trestles:
 Concrete ties for timber trestles, *Sept 25
 Replacing timber with steel and concrete, Sept 38E
 Used by MP on new line construction, *Nov 19
Tunnels:
 Adjustments easy with concrete roadbed, *May 30
 Cures rock falls with liner plates, *Jan 26
 Enlarge or daylight? (A), Apr 39
 Frisco photographs its clearances, *Apr 22
 How to stop leaks (A), Nov 32
 Trouble at SP's Potrero Hill tunnel, *Dec 20
 When to use rock bolts (A), Feb 35
Turnouts:
 Maintaining (A), Dec 32
 Maintenance and good intentions (E), Oct 8
Undercutting:
 Restores grades to yard tracks, *Dec 23
Union Pacific:
 Computer design of bridge piers, *Nov 24
U.S. Crosstie, Inc.:
 New manufacturing plant in production, *May 26
Waterproofing:
 Butyl rubber membrane for bridge decks, *Jan 22
 What determines type? (A), July 36
Weed and Brush Control:
 Machines lick brush problem on EL, *Aug 24
 Management attitude toward (E), Feb. 8
 Spray car adjusts dosages, *Feb 28
 What are the trends today?, *Feb 23
Welded Rail:
 Correcting pull-aparts in winter (A), June 28
 How the EL lays long strings, *Oct 26
 Positioning before laying (A), Nov 31
 Push-button plant cuts costs, *Feb 30
 Standard practice on merged line, *Jan 20
 Stretching welded rail (A), Apr 37
 Used for transit-line extension, *Oct 24
 What records to keep (A), Feb 38
 Will long bars eliminate pull-aparts? (A), Mar 74
Welding:
 Cored-wire electrode for rail-end build-up, *June 20
Winter:
 Coping with snow in North Country, *Aug 15
 New ideas in fight against snow, *Aug 26
 Use of "warm-weather" machines (E), Jan 8
Work Equipment:
 Computer system hikes machine output, *Mar 34
 Coping with snow in North Country, *Aug 15
 Machinery—Its care and operation, Sept 2E
 Machines lick brush problem on EL, *Aug 24
 Manufacturers forecast dramatic changes, Mar 41
 Modern tamper is springboard to progress, *Mar 38
 New ideas in fight against snow, *Aug 26
 Old fire apparatus fills need (E), Mar 8
 On/off-track machine speeds turnout tamping, *Mar 36
 Parking trucks at night (A), Aug 32
 Parts shipments need zip code, too (E), May 8
 Replacing engines on (A), June 30
 SCL uses two sets for rail laying, *July 17
 Test bench for hydraulic equipment, *Nov 22
 Tools and equipment for B&B men, Sept 42E
 Track-lining machine keeps moving, *Sept 34
 Trend in weed-spraying equipment, *Feb 24
 Type of pumps for B&B crews (A), Aug 35
 Use "warm-weather" units in winter (E), Jan 8
 What M/W men see ahead in tampers, Mar 44
 When to replace hydraulic hose (A), Apr 34
Yards:
 Maintaining run-through stands (A), Apr 36
 MP restores grades with undercutter, *Dec 23
 Picking up debris (A), Apr 30
 Use of secondhand track materials (A), Jan 40

New Products Index

*Illustrated Item

Abex Corp.:
 Weight-compensating car retarder, *Mar 62
Aeroquip Corp.:
 FT1013 Hose assembly machine, *July 30
Aldon Co., The:

Safety sign for car men, *Oct 30
Allied Steel & Tractor Products, Inc.:
 Model 9000 HO-PAC hydraulic pile hammer, *Nov 30
Allis-Chalmers Corp.:
 Model SB 2524 Sno-Bee snow thrower, *Oct 30
American Railroad Curving Co.:
 Trakcheck gage indicator, *Sept 39
Armco Steel Corp.:
 Hel-Cor helically welded corrugated pipe, *Nov 29

Baxter & Co., J. H.:
 Heart-Treated treating process for poles, *June 27

Bethlehem Steel Corp.:
 RQ-100B high-strength steel, Mar 52

Caterpillar Tractor Co.:
 Engine housing for D5 and D6C tractors, *July 30
 Hydraulic blade tip for No. 12F and No. 14F motor graders, *July 30
 Improved No. 120 motor grader, *Aug 30
 Improvements to No. 12F and 14E motor graders, *Aug 39
 New fiberglass canopy for D9G tractor, Mar 67
966 Series:
 Wheel loader, *July 29
Cox Co., W. T.:
 Model C-68 Rail-Road wheel attachment, *Feb 34

Edison Industries, Thomas A.:
Crystalaire Type F primary battery, *Mar 62

Egene Co.:
ERR-10 Switch anti-freeze lubricant, Nov 30

Fairmont Railway Motors, Inc.:
Hydraulic tie remover W115A, *Mar 56

Hydraulic tie shear W114 Series A, *Mar 64

Hy-Rail equipment Series 0306, *Sept. 39

Falcon Safety Products, Inc.:
Fast-Drying Falcon Epoxy coating, June 27

Goodyear Tire & Rubber Co.:
Neothane end posts, bushings, Apr 28

Hayes Track Appliance Co.:
PBF Blue Flag display, *Mar 54

Hogart Manufacturing Co.:
Steelplank for highway crossings, *Mar 52

Holland Co.:
Matisa Model 12-CB-8 undercut-cleaner, *Dec 26

Homelite:
Model XL-58 circular power saw, *Aug 30

XL-900 series chain saws, *Nov 29

Illsley, Doubleday & Co.:
Kerlube rail lubricator, *Sept 39

Jackson Vibrators, Inc.:
Model 4500 Surfacing-Liner, *Mar 38

Model 4500 surfacing-liner unit seen in operation on SCL, *July 24

Kalamazoo Manufacturing Co.:
Ballast Equalizer, *Mar 66

"Kal-Trac" brush cutter, *Mar 61

Tie destroyer, Mar 61

Kershaw Manufacturing Co.:
Tie Injector used on Burlington, *Dec. 14

Magnaflex, Inc.:
Magnetic-particle testing unit, *Apr 28

Martin Engineering Co.:
P.T.P. (post, tubing and piling) post driver, *May 32

Matisa Equipment Corp.:

Model 150 Compactamer, *Jan 30

Model 12-CB-8 Undercutter-cleaner, Dec 26

Series 80 Tamper-Liner-Leveler, *Sept 39

Melpar, Inc.:
Track geometry measuring system, *Nov 30

Mobil Oil Corp.:
Switch Heet switch heater, *July 29

Morrison Railway Supply Co.:
Damy ballast doors for hopper cars, *Mar 25

National Cylinder Gas Division:
NCG-Amsler Track Inspection System, *Mar 54

Scan structural clearance analyzer, *Mar 66

Nordberg Manufacturing Co.:
Spike-straightening machine, *Sept. 32

Osmose Wood Preserving Co.:
Pile-Gard pile protection, *Jan 32

Paxon-Mitchell Co.:
Model WHL hydraulic crane, *July 30

Plasser American Corp.:
AL 250 Track-Lining Machine, *Mar 54

Model AL 250 Automatic lining machine, *Sept 34

Plasermatic 06-16 Beaver tamper, *Mar 61

Universal Tamper 06-16SLC, *Sept 67

Professional Aids Co.:
Speed-Ruler for parallel lines, *Nov 30

Portec, Inc.:
Poly-Insulated rail joint, *Nov 30

Racine Hydraulics & Machinery, Inc.:
Guide-wheel kit for Anchor Fast, *Jan 30

Model "R" Recording Gauger, *Aug 30

"Plate Boy" ballast sweeper, *Dec 26

Rails Co., The:
Rail-Tec RTS gas switch heater, Mar 63

Railway Maintenance Corp.:
Auto-Spiker, *Mar 61

Car Mover/Front-End loader, *Mar 65

Concrete-Tie Clip applicator, *Mar 52

Rail drill-saw combination, *July 30

Universal AnchorMaster applicator, *July 29

Railway Track-Work Co.:
Model 5720-BP Tie Handler, *Feb 34

Ranco Industrial Products Corp.:
F-174-P Squeeze-Cote blacktop adhesive, *Mar 56

Nevygreen non-selective weed killer, *June 27

P-249 Epoxy sealer kits, *Mar 56

Remington Arms Co.:
Model P128 circular saw, *Oct 30

"Pin-Boy" 67 drive tool, *Dec 26

Vibrilite concrete vibrator, *Apr 28

Research Products Manufacturing Co.:
Model UR-IV Incinerator incinerating urinal, *Nov 29

Schroeder Brothers Corp.:
Hydra-Drive hydraulic test bench, *Aug 30

Model LFT In-Tank hydraulic line filter, *May 32

Suburban Propane Gas Corp.:
Propane gas rail heater, *Nov 29

Swiveler Co.:
Model 101 thrust-bearing swivel hook, *Feb 34

Tamper, Inc.:
Closed-circuit TV Indicator System, *Mar 56

Off-Tracking equipment for tampers, *May 32

Tong-type tie nipper for spike driver, *Mar 67

Turntable added to spike driver, *June 27

Templeton, Kenly & Co.:
Charger line of hydraulic pumps, *Oct 30

Thermex Metallurgical, Inc.:
In-track welding of compromise joint, *June 27

Thompson-Haywood Chemical:
Casoron G-10 weed and grass killer, *Jan 30

True Temper Corp.:
Cliploc rail tie clip, *Mar 63

Vapor Corp.:
Safety Flashing Light, Apr 28

Sno Gard switch heater, *Nov 29

Switch Rod Heater, *Mar 66

Wabco, S. & C. Division:
Carryphone III two-way radio, *Apr 28

West Chemical Products, Inc.:
Assault weed killer, Feb. 24

Woolery Machine Co.:
Rail heater, *Mar 65

Index to Authors

*Illustrated Article

Almy, W. D., Mar 74, Oct 34

Anderson, K. J., May 44

Annala, R. G., Apr 38

Ash, Edwin H., June 36

Barker, H. K., Aug 32

Batchelder, E. H., Sept 40

Belfield, A. Bruce, Sept 50

Bellinger, L. M., Mar 76, Apr 36

Billingsley, C. C., Oct 38

Blanchard, L. C., Apr 32

Bober, H., Sept 48

Bonner, G. T., Apr 37

Booth, H. E., July 33

Boott, William, Jan 43

Brauer, A. N., Oct 32

Brenton, G. W., June 34, Sept 41E

Bunker, R. E., Oct 44

Carlson, A. W., Nov 33

Carr, J. L., Sept 23E

Caywood, J. A., Sept 21E

Chambers, J. W., Sept 42E

Collins, J. R., June 28

Collins, J. S., June 34

Corbett, R. K., Sept 38E, Dec 36

Corey, W. E., Aug 34

Cowan, W., Dec 35

Cummings, E. M., Mar 75

Cushman, D. G., Mar 68

Danks, A. C., Nov 38

Davidson, J. W., Mar 70

Dean, W. E., July 32

Dennis, R. E., *Sept 7E

Dobranietski, E. B., Jan 37

Dove, R. E., *Oct 26

Dowdy, W. M., July 33, Sept 60

Dragos, P. R., May 34

Drew, F. P., *Jan 22

Drunsic, W. J., *May 20

Duffy, P. E., Nov 34

Fisher, R. J., Mar 70

Foley, V. C., *Aug 19

Forbes, L. G., June 35

Garcia, M. E., Nov 31

Garland, E. F., Feb 48

Fortney, E. O., Jan 41

Fox, W. M., Sept 50

Freeman, L. D., Sept 14E

Haacke, R. E., Oct 40

Hankins, V. C., Feb 35

Harbison, R. E., Mar 76

Harmsen, J. L., Feb 50

Hartsell, C. L., Dec 28

Hellwig, R. D., Oct 41

Henderson, J. E., Dec 30

Henry, G. E., May 34

Hewlett, L. B., Oct 40

Hicks, P. L., May 46

Hilton, T. G., Dec 28

Hodgkins, J. W., May 40

Hollaway, C. L., Dec 33

Howe, W. C., May 38

Huffman, F. H., Jan 39

Huhlein, G. P., May 33, Sept 40

Humphreys, W. C., Jan 34

Hunsberger, J. C., Sept 54

Hunter, J. T., Oct 32

Hursch, J. R., *Dec 17

Hutcheson, T. B., *Mar 8

Hutchinson, R. G., Apr 39

Jantz, R. N., Nov 36

Jasper, Joseph C., Oct 42

Johnson, E. Q., *Oct 22

Jones, W. J., July 36

Keeling, E. B., Sept 2E

Klein, C. A., Dec 39

Lamm, J. A. Jr., Feb 40

Lang, A. Scheffer, *May 24

Laycox, Tom, Jan 40

Lowman, Harry W., June 28

Lyons, D. F., May 37

Martini, C. P., Feb 38

Mays, J. W. N., Feb 46

McCormick, W. C., Sept 56

McFarling, W. K., Jan 33

Meek, H. V., Apr 37

Minetti, B. J., Feb 47, June 36

Mitchell, D. N., Aug 35

Mittlach, P. A., Aug 35

Moore, J. R., Dec 32

Morgan, L. P., May 33

Morrison, C. W., Dec. 34

Moynihan, J. C., Dec 34

Neuman, F. A., June 29

O'Shell, W. J., May 44

Palmer, R. E., Oct 43

Parker, A. C., Sept 28E

Parker, B. H., Apr 33

Ploudre, George W., *Nov 24

Poore, Stuart H., Sept 47

Prober, W. H., Sept 36E

Pullins, P., Apr 30

Rankin, W. H., Nov 37

Rear, G. W., Jr., Dec 36

Rees, F. L., Feb 45

Rentfrow, J. M., Dec 35

Risk, J. W., June 30

Robinson, C. L., Nov 32

Ruble, E. J., *Jan 22

Runde, E. E., Nov 32

Salmon, J. M. Jr., Nov 33

Salsman, J. D., Sept 10E

Sathre, C. O., July 34, July 36

Scheer, G. D., Dec 30

Schmitz, J. F., Feb 47

Schroeder, E. F., Nov 31

Sells, G. N., Sept 60

Sherman, L. L., June 32

Sickels, M. E., June 37

Siegel, E., Sept 52

Smith, D. E., Mar 74

Smith, Richard C., June 35

Stevens, D. W., Apr 35

Sweet, S. W., Nov 31

Terrill, V. R., Nov. 32

Thorson, R., Oct 43

Toal, T. W., July 36

Uhrich, R. H., Dec 33

Vanderpool, G. R., Sept 43E

Wachter, C. E., Dec. 39

Wang, A. B., Jan 42, Feb 35, 47, Mar 68, Apr 30, June 29, 34, July 38, Aug 36, 39, Oct 36, Dec 40

Williams, J. R., Sept 33E

Williams, T. S., Jan 35

Williamson, H. M., *Dec 20

Wilson, H. M., Oct 34

Withrow, N. R., Feb 44

Woxland, M. O., Sept 50

Zipperian, G. L., Apr 34, Aug 32